


# TECHNICAL BULLETIN

## TRAILER AIR SUSPENSIONS

**No:** 97117-120  
**Subject:** AANT 230 Hanger Repair Kit  
**Date:** May 2004 **Revision:** C



It has been reported that in some instances the top clevis assembly for the shock absorber has broken away from the hanger wing.

In order to improve repair times, the quality of the repair and reduce customer downtime, Hendrickson Asia Pacific wish to advise Authorised Repairers that a Repair Kit has been released to facilitate this.

### **COMPONENTS**

There are two (2) kits repair kits that are available. One for the Left Hand Hangers (98544-042) and one for the Right Hand Hangers (98544-043).

There are two (2) parts in these kits, A gusset (Fig.3) and a front plate (Fig.1).

Note: Boomerang (Fig.2) as shown is no longer required.

These can be purchase through an Authorised Hendrickson Parts outlet.

The Gusset as shown (Fig. 3) is available as a separate item if required. Part No 98870-033 for the left and 98870-034 for the right.

### **PROCEDURE**

The fitting instructions are contained in these kits.

If further assistance in understanding or implementing this is required, contact the Hendrickson Product Support Department on 03 9767 3400 or [technicalservice@hendrickson.com.au](mailto:technicalservice@hendrickson.com.au)

**IMPORTANT - HENDRICKSON REMINDS USERS THE USE OF A MODIFIED OR SUBSTITUTE PART IS NOT RECOMMENDED BECAUSE THE PART MAY NOT MEET HENDRICKSON'S SPECIFICATIONS, WHICH COULD LEAD TO FAILURE OF THE PART, LOSS OF VEHICLE CONTROL AND PERSONAL INJURY.**

**THIS BULLETIN CONTAINS PRODUCT IMPROVEMENT INFORMATION ONLY.**

**HENDRICKSON IS NOT COMMITTED OR LIABLE FOR CANVASSING OF EXISTING PRODUCT.**