

H[®] TECHNICAL BULLETIN INTRAAX[®]/VANTRAAX SUSPENSIONS

NO: B43

SUBJECT: AA250 Air Spring Upgrade


DATE: November 1999

REVISION: A

When installing or replacing the air springs on the AA250 (S-21784) INTRAAX[®] Suspension, the metal air spring support disk *must* be installed.

Tighten the air spring fasteners:

- Upper Air Spring Nut: 80-100 ft-lbs (108-136 N•m)
- Lower Air Spring Nut: 25-35 ft-lbs (34-47N•m)



2070 Industrial Place SE
Canton, Ohio 44720-2600 USA
Phone (330) 456-7288
Fax (330) 456-0105

H[®] HENDRICKSON
Trailer Suspension Systems

A Boler Company

250 Chrysler Drive, Unit #3
Brampton, Ontario L6S 6B6 CAN
Phone (905) 789-1030
Fax (905) 789-1033