


TECHNICAL BULLETIN

HAS TRUCK AIR SUSPENSIONS HEIGHT CONTROL VALVE IMPROVEMENT

No: TRUCK AUS -016
Subject: HCV Exhaust Port Filter
Date: JULY 2002 **Revision:** A



As part of our continuous product improvement program, Hendrickson wish to advise general improvement information on all truck height control valves

HCV EXHAUST

Hendrickson installation instructions indicate the fitment of 3/8" nylon tubing approximately 500mm long to the exhaust port of the valve.

This has now been replaced with a filter to prevent the ingress of contaminants.

This item is now standard fitment and is contained in all new kits as well as replacement Height Control Valves.

The non fitment of this item may allow dirt to enter and cause premature failure of the HCV.

This bulletin is for maintenance information only and is not a product revision or upgrade.

If further information or assistance is required, Please contact the Hendrickson Customer Excellence Centre on (03) 9767 3400.

This bulletin contains product improvement information only. Hendrickson is not committed or liable for canvassing of existing product.

WARNING - HENDRICKSON REMINDS USERS TO ADHERE TO THE PUBLISHED CAPACITY RATINGS FOR SUSPENSIONS.

DO NOT MODIFY PARTS OTHER THAN OUTLINED IN THIS PUBLICATION.